

Oil Field Environmental Incident Summary

Incident: 20150106160503 **Date/Time of Notice:** 01/06/2015 16:05

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: ERICKSON 12X-35

Field Name: CAPA

Well File #: 19117

Date Incident: 1/6/2015 **Time Incident:** 09:30

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 95

Sec: 35

Qtr:

Location Description:

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
P.O Box 6506
325 22ND AVE E
WILLISTON, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	Barrels	15	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None- spill was contained within lined metal berm and on location

Areal Extent:

Potential Environmental Impacts:

None- spill was contained within lined metal berm and on location

Action Taken or Planned:

Recovered oil will be returned to the production tanks. Any impacted material will be hauled to an approved disposal facility.

Wastes Disposal Location: R360

Agencies Involved:

Updates

Date: 1/7/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas on location. NDIC retains oversight.